



Contract No. C-9385	Station JW 70+00 - JW 139+78	Mile/Line: JW	C/S
Staked by WSDOT 10/7/2019	Date 	Work Started Date 8/8/2019	Work Completed Date
Calculated by Dean A. Long 9/1/2020	Date 	Checked by Mark Lee 9/14/2020	Date
		Inspector Scott Busby	Date 7/27/20

Bid Item 093

CONSTRUCTION GEOTEXTILE FOR PERMANENT EROSION CONTROL

Group # 1

Square Yards (S.Y.)

Estimate # 21

\$/Unit: \$3.00 - Round to nearest Whole Number

Date / Station / Calc. / Quantity

Group 01

On 7/27/2020 Unsuitable material was encountered. The unsuitable excavation and Quarry Spalls were paid for on Estimate 20 but the Geotextile was inadvertently missed. This FNR corrects that oversight.

07/27/2020.....LW 521+80 to LW 518+25.....Width = 20'
 355 LF + 2' each side = 359 LF
 20 LF wide + 2' each side = 24 LF
 355' x 24' = 8,616 SF / 9 SY/SF = 957.33 SY.....Round to Whole Number.....
957 SY

07/27/2020.....LW 516+60 to LW 516+80.....Width = 5.25'
 20 LF + 2' each side = 24 LF
 5.25 LF wide + 2' each side = 9.25 LF
 24' x 9.25' = 222 SF / 9 SY/SF = 24.67 SY.....Round to Whole Number.....**25 SY**

Total Group 01 = 957 SY + 25 SY = 254.03round to..... **982 SY**

OK TO PAY 982 SY Group 01

Excavation depth of 2' was approved by Clint Bucknell, thus the 2' addition of material on each side.

Lengths and Widths based on GPS measurements by Justin Perez (WSDOT Survey)

Item Num	Material Brand Name/Model Type	Manufacturer	Brand Name/Model Type	RAMS/QPL Ref. No.	Appr/Acc Code	Basis of Accept
093.01	Ditch Lining Woven	TenCate Mirafi	180N	QPL-0001	7021 /	Mfr's Certificate of Compliance per Std. Spec. 9-33.4(4)

Item Num	Item Description	Grp	Date Work Complete	Unit	Quantity	Ledger Entry No.	Posted By Init.	Posted By Date	Checked By Init.	Checked By Date	Est. No.
0093	CONSTRUCTION GEOTEXTILE FOR PERMANENT EROSION CONTROL	01	9/5/2020	S.Y.	982	777	MEL	09/15/20			21

Attachments

 File Attachment

DOT Form IP 422-635ER EF
Revised 4/2009